

Failure code [DBNCMA] MISMATCH) OPT-Setting (M/C)

Action level	Failure code	Failure	Inconsistency of Option Selection (master controller system)
L01	DBNCMA		
Detail of failure	The option setting of monitor panel differs from that stored in master controller memory.		
Action of controller	- Operates with the setting stored in master controller memory. [Resetting condition] - Turn the starting switch to OFF position.		
Problem on lift truck	If the actual installation state of optional equipment differs from the setting stored in the memory, error detection is generated by failure detection.		
Related information	- This error code may be detected when master controller or monitor panel is replaced. - This error code may be detected when memory error of master controller or monitor panel is generated. - Method of reproducing failure code: Turn the starting switch to ON position.		

No.	Cause	Procedure, measuring location, criteria and remarks
1	Inconsistency by replacing master controller or monitor panel	Perform option setting of monitor panel.